

File Edit Actions Options Analysis DFM Step Rout Windows

Help

Job : 2v29uu41a0

Step: set

Job Matrix ...

☐ to
☐ ts
☐ plncs
☐ cs
☐ plnss
☐ ss
☐ bs
☒ drl
☐ ldi
☐ rout
☐ no_cooper
☐ v-cut
☐ bp
☐ tp
☐ ydkdrl
☐ fzkdrl
☐ d
☐ ts.d
☐ cs.d
☐ ss.d
☐ bs.d
☐ drl.d
☐ npdrl.d
☐ rout.d
☐ no_cooper.d
☐ v-cut.d

Drill Tool Manager

Layer : Slots:

Board Thickness : my User Parameters :

	Tool	Count	Slot Len(my)	Type	Finish Size(my)	+Tol (my)	-Tol (my)	Drill Size(my)	Drill Des
☒	T01	4		NPlated ☐	3000	0	0	3000	
☒	T04	224		NPlated ☐	500	0	0	500	
	Total	228							

T01 First <-- --> Last Index: ml/my

Combine Tools Merge Tools : Update Tools Numbers ☐ Merge

Apply Calc Drills Update Table Close