

Job : 4g00g075a0


Step: cam

Job Matrix ...

- ☐ to
- ☐ ts
- ☐ plncs
- ☐ cs
- ☐ sig2t
- ☐ sig3b
- ☐ plnss
- ☐ ss
- ☐ bs
- ☐ bo
- ☐ drl
- ☐ ldi
- ☐ rout
- ☐ v-cut
- ☐ fzkdr1
- ☐ cvia
- ☐ tp
- ☐ bp
- ☐ qd1
- ☐ qg1
- ☐ gko
- ☐ gm3
- ☐ pb
- ☐ pt
- ☐ npth
- ☐ d
- ☐ to.d
- ☐ ts.d
- ☐ cs.d
- ☐ sig2t.d
- ☐ sig3b.d
- ☐ ss.d
- ☐ bs.d
- ☐ bo.d
- ☐ drl.d
- ☐ rout.d

Selected : 0

现在按不允许绿油冒方法做的，那么这个孔要在TS面加比孔小3MIL的正量。



X = -5.910513mm
Y = 36.050275mm

X Y : <M> - Select first area corner

DX=-1.500125,DY=0,D=1.500125

MM