

Job : 4v0156ana0

Step: set

Job Matrix ...

☐ datecode-to

☐ to

☐ ts

☐ plncs

☐ cs

☐ sig2t

☐ sig3b

☐ plnss

☐ ss

☒ bs

☐ drl

☐ cvia

☐ ldi

☐ rout

☐ tp

☐ bp

☐ dd

☐ outline

☐ lnp-drl

☐ ydkdrl

☐ npth

☐ d

☐ to.d

☐ ts.d

☐ cs.d

☐ sig2t.d

☐ sig3b.d

☐ ss.d

☐ bs.d

☐ drl.d

Drill Tool Manager

Layer :		drl		Slots:		Yes			
Board Thickness :		1600 my		User Parameters :		hasl			
	Tool	Count	Slot Len(my)	Type	Finish Size(my)	+Tol (my)	-Tol (my)	Drill Size(my)	Drill Des
☒	T01	300		NPlated	500	50	50	500	
☒	T02	4		NPlated	2000	50	50	2000	
	Total	304							

T01
First
<--
-->
Last
Index:

ml/my
Regular

Combine Tools
Merge Tools :
Update Tools Numbers
Merge

Apply
Calc Drills
Update Table
Close