

Job : 2s04507ca0

Step: cam

Job Matrix ...

☐ CS

☐ plnss

Features Histogram Popup

Layer : drl.d

File Edit

Total Features = 203

Pads List

POS	r200.66	2
POS	r254	33
POS	r381	14
POS	r508	1
POS	r762	5
POS	r899.16	48
POS	r939.8	96
POS	r2794	4
Total		203

Highlight

Turn Off

Update

Close

pt.d

to.d

Drill Tool Manager

Layer : drl Slots: Yes

Board Thickness : 1600 my User Parameters : hasl

	Tool	Count	Slot Len(my)	Type	Finish Size(my)	+Tol (my)	-Tol (my)	Drill Size(my)	Drill Des
+A	T01	2		Via	300	0	0	400	
+B	T02	2		Plated	350	0	0	450	
+C	T03	2		Via	500	0	0	600	
+D	T04	1		Via	600	0	0	700	
+E	T05	5		Plated	762	0	0	900	
+F	T06	48		Plated	899.16	0	0	1000	
+G	T07	96		Plated	939.8	0	0	1050	
+H	T08	4		NPlated	2794	0	0	2800	
+I	T09	31		Via	350	0	0	450	
+J	T10	12		Plated	500	0	0	600	
	Total	203							

T01

First

<--

-->

Last

Index:

ml/my

Regular

Combine Tools

Merge Tools :

Update Tools Numbers

Merge