

Job : 4a17900ta0

Step: cam

Job Matrix ...

☐ to
☐ ts
☐ plncs
☐ cs
☐ sig2t
☐ sig3b
☐ plnss
☒ ss
☐ bs
☐ bo
☐ drl
☐ cvia
☐ ldi
☐ rout

☐ tp
☐ bp
☐ dd
☐ d
☐ to.d
☐ ts.d
☐ cs.d
☐ sig2t.d
☐ sig3b.d
☐ ss.d
☐ bs.d
☐ bo.d
☐ drl.d
☐ rout.d
☐ bp.d
☐ dd.d
☐ tp.d
☐ 1

Results viewer

Signal Layer Checks

None Layers All Categories (21) Meas: All


cs
sig2t
sig3b
ss

Pad to pad (94)
Pad to circuit (719)
Circuit to circuit (690)
Same Net Spacing (174)
PTH to Copper (228)
PTH (Comp) Annular ring (86)

First <--- ---> Last Index: 6816

Auto Zoom Sv: Show All

Replace layers



Solder Mask Checks

Parameters...

Ranges...

25 Jul 2013
10:42 AM - 0:00:04