

File Edit Actions Options Analysis DFM Step Rout Windows

Job : 4x0ck03wa0

Step: cam

Job Matrix ...

☐	ts
☒	cs
☐	sig2b
☐	sig3t
☐	ss
☐	bs
☐	dr1
☒	dr11-2
☐	dr13-4
☐	ldi
☐	rout
☐	tp
☐	bp
☐	cvia
☐	npth
☐	fzt

Results viewer

Drill Checks

None Layers All Categories (5) Meas: All

dr1

dr11-2

dr13-4

ldi

PTH Summary (6)

NPTH Summary (12)

Via Summary (129)

Close Holes (151)

NPTH to Rout (31)

First <---> Last Index: 246

Auto Zoom Sv: Show All

Replace layers

dr11-2 3.952mil r15.748 r15.748

Close

Results histogram

Count

Average

Sum

Min

Max

1

3.9-

4

Spacing

Hole 1

Hole 2

DEL REF

151 measur

REF--> closeh = 12 15 20

corner