

Job : 2a97z11ta0

Step: set

Job Matrix ...

- ☐ plnss
- ☐ ss
- ☐ bs
- ☐ drl
- ☐ ldi
- ☐ rout
- ☐ cvia
- ☐ datecode-ts
- ☐ bp
- ☐ dimension
- ☐ tp
- ☐ panel_to
- ☐ panel_ts
- ☐ panel_cs
- ☐ panel_ss
- ☐ panel_bs
- ☐ panel_bo
- ☐ panel-milll
- ☐ panel_npthk
- ☐ panel
- ☐ ydkdrl
- ☐ d
- ☐ ts.d
- ☐ cs.d
- ☐ ss.d
- ☐ bs.d
- ☐ drl.d
- ☐ rout.d
- ☐ bp.d
- ☐ dimension.d
- ☐ tp.d
- ☐ panel_to.d
- ☐ panel_ts.d
- ☒ panel_cs.d
- ☐ panel_ss.d
- ☐ panel_bs.d
- ☐ panel_bo.d
- ☐ panel-will

Selected : 0



X = -0.154
Y = 3.628