


File Edit Actions Options Analysis DFM Step Rout Windows

Job : 4b0310c0a0

Step: cam.orig

Job Matrix ...

- ☐ to
- ☐ ts
- ☐ plncs
- ☐ cs
- ☐ pln2t
- ☐ sig2t
- ☐ pln3b
- ☐ sig3b
- ☐ plnss
- ☐ ss
- ☐ bs
- ☐ bo
- ☐ drl
- ☐ ldi
- ☐ rout
- ☐ cvia



Results histogram

Count

Average

Sum

Min


Max

Spacing

DEL

REF

Size (Spacing) / Min (Spacing)



Spacing

Resolution

SM

1.0



DEL

REF

1596 measurements for 2 layers

Close

Results viewer

Silk Screen Checks

None Layers All

Categories (12)

Meas: All

- to
- bo

- SM Clearance (1596)
- SMD Clearance (1131)
- PTH pads Clearance (59)
- Via pads Clearance (18)
- Undrilled pads Clearance (1125)
- NPTH clearance (2)

First <--- ---> Last Index: 12

Silk Screen Check

Parameters...