

File Edit Actions Options Analysis DFM Step Rou

Job : 6v2214nfa0

Step: coupon

Job Matrix ...

☐ n7262.pdf

☐ to

☐ ts

☐ plncs

☐ cs

☐ sig2t

☐ sig3b

☐ sig4t

☐ sig5b

☐ plnss

☐ ss

☐ bs

☐ bo

☒ drl

☐ 2rd

☐ ldi

☐ rout

☐ tp

☐ bp

☐ np1

☐ npth

☐ cvia

☐ v-cut

☐ d

☐ ts.d

☐ cs.d

☐ sig2t.d

☐ sig3b.d

☐ sig4t.d

☐ sig5b.d

Drill Tool Manager

Layer : 
 Slots:

Board Thickness :  ml
 User Parameters :

|                                     | Tool  | Count | Slot Len(ml) | Type   | Finish Size(ml) | +Tol (ml) | -Tol (ml) | Drill Size(ml) | Drill Des | Si |
|-------------------------------------|-------|-------|--------------|--------|-----------------|-----------|-----------|----------------|-----------|----|
| <input checked="" type="checkbox"/> | T01   | 2     |              | Via    | 12              | 0         | 0         | 9.843          |           |    |
| <input checked="" type="checkbox"/> | T02   | 2     |              | Plated | 32              | 3         | 3         | 35.433         |           |    |
|                                     | Total | 4     |              |        |                 |           |           |                |           |    |

T02

First <-- --> Last

Index:

ml/my

Regular

Combine Tools

Merge Tools :

Merge

Apply

Calc Drills

Update Table

Close

